

CLASSIFIED MESSAGE

Approved For Release 2002/10/25 : CIA-RDP74B00836R000100030017-9

16.17

25X1A ORIG: [REDACTED]
 25X1A UNIT: IDEAL/OSA
 25X1A EXT: [REDACTED]
 DATE: 1 DEC 70

TOP SECRET

1	IDEA	9	COVER
2	IDEA	10	
3	D/SA	11	
4	D/O	12	
5	D/M	13	
6	SS	14	
7	CC	15	
8	RB	16	

DEFERRED	PRIORITY	INITIALS
ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO :

FROM:

CONF:

INFO:

1 DEC 70 15 52Z

TO TOP SECRET

INFO

CITE

678

25X1A PRIORITY [REDACTED]
 IDEALIST/SCOPE SALE

25X1A

25X1A 25X1 REF: [REDACTED]
 SUBJECT: ACCIDENT BOARD FINDINGS

1. DETACHMENT "H" U-2R 057 CRASHED [REDACTED]

25X1A

25X1A [REDACTED] AT 0640Z 24 NOVEMBER 1970. THE AIRCRAFT WAS COMPLETELY
 25X1A DESTROYED ON IMPACT AND THE [REDACTED] PILOT WAS FATALY INJURED.

25X1A 2. THE PURPOSE OF THIS TRAINING MISSION WAS ROUTINE HIGH
 ALTITUDE PROFICIENCY FLIGHT FOR THE PILOT. THE AIRCRAFT DEPARTED
 [REDACTED] ON A SCHEDULED 0215Z TAKE OFF AND APPARENTLY FLEW THE
 PLANNED BOUND ROBIN TRAINING ROUTE. DURING THE APPROACH FOR
 LANDING, THE MOBILE CONTROL OFFICER OBSERVED WHAT APPEARED TO BE
 A NORMAL APPROACH TO RUNWAY 05. AT TOUCHDOWN APPROXIMATELY 1200
 FEET FROM APPROACH END OF RUNWAY, THE AIRCRAFT SKIPPED SLIGHTLY
 AND TOUCHED DOWN A SECOND TIME IN A RIGHT DRIFT. AT THIS POINT,
 AIRCRAFT STARTED OFF THE RUNWAY TO THE RIGHT, CROSSED A TAXIWAY
 AND STRUCK A 6½ FOOT HIGH RUNWAY MARKER ADJACENT TO THE TAXIWAY AND

COORDINATING OFFICERS

TOP SECRET

RELEASING OFFICER

Approved For Release 2002/10/25 : CIA-RDP74B00836R000100030017-9

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

AUTHENTICATING OFFICER

Copy No.

CLASSIFIED MESSAGE

ORIG :
UNIT :
EXT :
DATE :

TOP SECRET

1		9	
2		10	
3		11	
4		12	
5		13	
6		14	
7		15	
8		16	
PRIORITY	DEFERRED	PRIORITY	INITIALS
	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO :
FROM :
CONF :
INFO :

PAGE 2

TO INFO CITE
THEN CONTINUED ON ACROSS THE INFIELD. AS THE AIRCRAFT STRUCK THE RUNWAY MARKER, MOBILE CONTROL NOTED AN INCREASE IN POWER INDICATING AN ATTEMPTED GO AROUND. THE AIRCRAFT AGAIN LEFT THE GROUND, APPROXIMATELY 2600 FEET FROM THE APPROACH END OF THE RUNWAY, AND STARTED A SLOW LEFT CLIMBING TURN WITH NOSE HIGH. FROM THIS NOSE HIGH LEFT BANK ATTITUDE, THE AIRCRAFT APPARENTLY STALLED, HIT THE GROUND AND STARTED BURNING APPROXIMATELY 100 FEET TO THE LEFT OF THE RUNWAY. WEATHER AT TIME OF THE ACCIDENT WAS 2,000 FEET SCATTERED, 7 MILES VISIBILITY AND WIND AT 12 KNOTS FROM 100 DEGREES.

3. THE ACCIDENT BOARD HAS COMPLETED ITS DELIBERATIONS AND ITS CONCLUSIONS FOLLOW:

A. THE PRIMARY CAUSE OF THE ACCIDENT WAS DETERMINED TO BE PILOT FACTOR IN THAT WHILE ATTEMPTING A GO AROUND FROM A POOR LANDING, THE PILOT ENTERED A MANEUVER FROM WHICH HE WAS UNABLE TO RECOVER.

B. A CONTRIBUTING CAUSE WAS THE CROSSWIND CONDITION.

COORDINATING OFFICERS

TOP SECRET

RELEASING OFFICER

Approved For Release 2002/10/25 : CIA-RDP74B00836R000100030017-9

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

GROUP 1
Excluded from automatic
downgrading and
declassification

AUTHENTICATING OFFICER

Copy No.

CLASSIFIED MESSAGE

ORIG :
UNIT :
EXT :
DATE :

TOP SECRET

1		9	
2		10	
3		11	
4		12	
5		13	
6		14	
7		15	
8		16	
	DEFERRED	PRIORITY	INITIALS
	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO :
FROM :
CONF :
INFO :

PAGE 3

TO

INFO

CITE

THIS CONTRIBUTED TO THE POOR LANDING AND SUBSEQUENT LOSS OF
DIRECTIONAL CONTROL WHICH LED TO THE PILOT'S DECISION TO
INITIATE A GO AROUND EVENTUALLY RESULTING IN THE ACCIDENT.

END OF MESSAGE

25X1A

25X1A

--

COORDINATING OFFICERS

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

--

AD/O/OSA
RELEASING OFFICER

AC/IDEA/OSA
AUTHENTICATING OFFICER